

# BULLETIN

## Licensed Vehicle Testers



Reference No: LVT 01-18

Date issued: 15/03/2018

### Increased Focus on Vehicle Inspections

In their February newsletter VicRoads has stated that as part of the auditing program, the registration and licensing compliance team, will be increasing its compliance focus on vehicle inspections at VicRoads customer service centers. These spot checks are designed to identify issues relating to an LVT conducting a road worthy on a vehicle. As a result, VACC is aware that several LVTs have shown a shortfall in the roadworthy process in the following areas:

- oil leaks from engine and other components;
- structural damage;
- tyres not within wear limits;
- condition of windscreen wipers;
- condition of brake lines and other components;
- cracks within windscreens, please ensure you take photographs with measurements;
- condition of suspension bushes and other components;

Please ensure you follow instructions as published in VicRoads vehicle standards information, testing times, newsletters and training material provided by TAFE providers. Also, be aware that VACC are here to assist and would like to hear from you should any issues arise, we can also connect you with a peer member you can speak to over the phone if you require technical support.

Please feel free to contact me to discuss.

Regards

**John Houry**  
**Industry Policy Adviser**  
Industrial Relations, Policy, Training and Engagement  
**VACC**  
Level 7 | 464 St Kilda Road | Melbourne Vic 3004  
P: 03 9829 1153 | M: 0412 510 108 | W: [vacc.com.au](http://vacc.com.au)